Schritt 4/4 • Step 4/4



Entfernen Sie Abdeckung 2 nach dem Anbringen der Schutzfolie. Peel off mask 2 after the application is completed.



SL-3453

© 2012 Jöllenbeck GmbH.

All rights reserved. SPEEDLINK®, the SPEEDLINK word mark and the SPEEDLINK swoosh are registered trademarks of Jöllenbeck GmbH. Jöllenbeck GmbH shall not be made liable for any errors that may appear in this manual. Information contained herein is subject to chance without prior notice.

All trademarks are the property of their respective owner. Please keep this information in a safe place for later reference.

JÖLLENBECK GmbH, Kreuzberg 2 27404 Weertzen, GERMANY

● ● www.speedlink.com ● ● ●




Anbringen der Schutzfolie

Applying the Screen Protection



Schritt 1/4 • Step 1/4



Bitte beachten Sie, dass die Schutzfolie (D) is enclosed by two masks (1+2).

von zwei Abdeckungen umschlossen ist. Please note that the protective film (D)

Schritt 2/4 • Step 2/4



Entfernen Sie vorsichtig Abdeckung 1 und berühren Sie hierbei nicht die Klebeseite. Peel off mask 1 carefully and take care not to touch the adhesive side.

Schritt 3/4 • Step 3/4



Richten Sie die Schutzfolie (D) an die Ecken des Displays aus und streichen Sie sie mit dem Folienwerkzeug glatt.

Alian the protective film (D) with the edges of the screen and plane it with the applicator.